Tanks Data	30 DAYS WALK THROUGH INSPECTION					
UST Facility I.D.((FID) # 1/505	Contact Number					
Facility Name CTTOO	Contact email					
Address 4 70 1 Dagadury 4 5 400	Date of Inspection 69-68-703					
Operator on Duty Name	Name of the Person Conducting Inspection					
Op	erator Train	ing		0	Oia	
Operator Training current	Yes	ONo	OperatorNotified	Yes	ON0	
Is Registration current with correct owner, operator etc.	tion/Notificat OYes	ONO	OperatorNotified	Ores	Oto	
Release Detection Method	elease Detection	On SCIM	OSIR	Orc	Other	
Make and Model RTL>-3 Does it have paper?	S Yes	ONO	OperatorNotified	Yes	Oī _o	
Is it in Alarm mode?	Yes	(PNO	OperatorNotified	OY'es	O40	
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	Oio	
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Yes	Ovo	
[일본) 등 집단 시간	Spill Buckets					
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	9 No	OperatorNotified	Oes	Oio	
Are the Spill Bucket in good condition and free of damage/cracks	Yes	QNo	OperatorNotified	Oes	Ovo	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Fill Ports Yes	Ovo	OperatorNotified	Ofes	O ₁ o	
Pip	ping/STP Sun			0		
Are Sumps Clean and free from water, debris, product etc?	Yes	Oyo	OperatorNotified	Vres	O _{NO}	
Under Dispe		ments (UDC)		0		
ATO I III & DIEMII CHILL II LO II LAM II MONA MANAMAN PARAMANA	Yes	ONO	OperatorNotified		Oio	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO	OSSED OFF A	ACCORDING CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	JLATIONS	
perator on Duty Name		Signature		Date		
	tanksdata@gmail.com				www.tanksdata.com	