Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID)# 1/505	Contact Num	Contact Number			
Facility Name	Contact email	Contact email			
Address 4700 Brookway 4640	8 Date of Inspec	tion O	025		
Operator on Duty Name	Name of the P Conducting In		Gurpereet		
	Operator Training				
Operator Training current	OYes (ONo .	OperatorNotified	Yes	ONo
[[마다 아마리 : [[마다 나이에 의로 12] 14일 이 12의 아는 어때에 되었다. (14일) [[마다 아마리 : [[마다 아마리 : [[마다 하다 : [[마다 하다 : [[마다 : [[[마다 : [[[마다 : [[[] : [[[] : [[[] : [[Registration/Notification	Form			
Is Registration current with correct owner, operator e		UNO.	OperatorNotified	Ves	Olo
Release Detection Method	Release Detection	~	ORID	Orc	
Make and Model URTCS	ATG	DIM	Obite	Oic	Miner
Does it have paper?	Yes	No	OperatorNotified	Yes	Oio
Is it in Alarm mode?	Yes	No	OperatorNotifled	Yes	No
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	\mathcal{H}_{in}
Necessary Monthly Printout Taken	Yes	XNo.	OperatorNotified	Yes	Xio
110000001 involution and and	Spill Buckets	0.0	Operatoritosarea	0.0	
Are Spill Buckets Clean and free from water, debris, produ		ONO	OperatorNotified	0	
Are the Spill Bucket in good condition and free of damage		No	OperatorNotified	es	Xio
And the phin properting good continuon and may be or distingly	Fill Ports	0"	O per mor rionited	0.	
Is Fill pipe cap tight and fill pipe free from any obstruct		No	OperatorNotified	Tes	(No
	Piping/STP Sump	18			
Are Sumps Clean and free from water, debris, product etc		(No	OperatorNotified	Yes	(No
Und	er Dispenser Containm	ents (UDC)			
Are UDCs clean and free from water, debris, product	etc? Yes	ONO	OperatorNotifled	Ores	Oio
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST I FOLLOWING PROF	BE DISPOSSED OFF AC			S AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215	tanksdata@gmail.com	n		www.tanks	data.com
					2022041

MARKATA L