	30 DAYS	WALK THROUGI	HINSPECTIC	N
Tanks Data	Contact Number			
UST Facility I.D.((FID) # 2-5-0	Contact email Date of Inspection $0.6-10-2.35$			
Facility Name (COC)				
Address 2 490 Clark Rd 46409				
Operator on Duty Name	Conducting Inspection	Cruprolt		
	perator Training Yes No	OperatorNotified	OYes C	No
Operator Training current Registra Is Registration current with correct owner, Gerator etc.	Yes No	OperatorNotified	Ores C)io
Is Registration current with correct owner, speciator or Release Detection Method	elease Detection	SIR	Orc C	ther
Make and Model $VRTZS-7$. Does it have paper?	SO Yes ONo	OperatorNotified		210
	Yes No	OperatorNotified	QYes _	₹NO
Is it in Alarm mode?	Yes No	OperatorNotified	Ores C	No
Interstitial Monitoring Sensor Status Normal Necessary Monthly Printout Taken	es ONo	OperatorNotified	O'es C)No
	Spill Buckets	OperatorNotified	Øjes (No
Are Spill Buckets Clean and free from water, debris, product etc? Are the Spill Bucket in good condition and free of damage/cracks	Ores ONo	OperatorNotified	Ses C	510
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes No	OperatorNotified	Oes C)io
P	iping/STP Sumps		0.	\r_
Are Sumps Clean and free from water, debris, broduct etc?	OYes (No	OperatorNotified	Wes ()°°
Under Disp	enser Containments (UD	C)		\.
Are UDCs clean and free from water, debris, product etc?	OYes WNo	OperatorNotified		No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISH FOLLOWING PROPER PRO	POSSED OFF ACCORDING	G TO EXISTING RULES D CONTRACTOR.		
	Signatur		Date 0 6 -	10-208
Operator on Duty Name	data@gmail.com		www.tanksdata.com	n
317-645-0215 tanks	data de Britanio			20220516