Tanks Data	3	0 DAYS WA	LK THROUGH	INSPEC	TION	
UST Facility I.D.((FID) # 5721)	Contact Nu	Contact Number				
Facility Name (TTGO	Contact en	Contact email				
Address 4575 w 37 (1411, 4/34)	Date of Ins	Date of Inspection 17-06-702				
Operator on Duty Name		Name of the Person Conducting Inspection  Aurles of				
0	perator Train					
Operator Training current	Yes	ONo	OperatorNotified	Yes	ONo	
	tion/Notificat	tion Form		_		
Is Registration current with correct owner, operator etc.	Yes	ONO	OperatorNotified	Ves	Olo	
	elease Detecti	ion				
Release Detection Method	ATG	CIM	SIR	OIC	Other	
Make and Model URTES-)	56					
Does it have paper?	Yes	QN <sub>0</sub>	OperatorNotified	Yes	Q10	
Is it in Alarm mode?	Yes	ONO	OperatorNotified	Yes	Q10	
Interstitial Monitoring Sensor Status Normal	Yes	ONO	OperatorNotified	Yes	Oyo	
Necessary Monthly Printout Taken	Yes	ONo	OperatorNotified	Tes	Ovo	
	Spill Bucket	s				
Are Spill Buckets Clean and free from water, debris, product etc?	O'res	(2)No	OperatorNotified	(7)es	Olo	
Are the Spill Bucket in good condition and free of damage/cracks	Yes Fill Ports	O <sub>No</sub>	OperatorNotified	Ges	O <sub>10</sub>	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	No	OperatorNotified	Tes	Oko	
사진 사람들은 아이들이 얼마나 가는 아이들이 아이들이 아이들이 아이들이 아이들이 아이들이 아이들이 아이들	ping/STP Sur	$\cup$		0		
Are Sumps Clean and free from water, debris, product etc?	Yes	No	OperatorNotified	Yes	No	
Under Dispe	enser Contain	ments (UDC)		4		
Are UDCs clean and free from water, debris, product etc?	Yes	ONO	OperatorNotified	(2) res	Oio	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO				AND REQU	LATIONS	
Operator on Duty Name		Signature		Date	200 Date	
317-645-0215 tanks	data@gmail.c	om		www.tanks	data.com	