Tanks Data	30	DAYS WA	LKTHROUGE	IINSPEC	TION
UST Facility I.D.((FID) # 5 71/1	Contact Number				
Facility Name (TTGO	Contact email				
Address 4575324h ANN6342	Date of Inspection 08-08-708				
	Name of the Person Conducting Inspection Cuty/Zell				
Op	erator Trainin	g	/		
Operator Training current	Yes	ONo.	OperatorNotified	Yes	ONO
Is Registration current with correct owner, operator etc.	ion/Notificatio	ONO	OperatorNotified	Ores	Oio
Release Detection Method	lease Detection	CIM	OSIR	OIC	Other
Make and Model / \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Yes	()No	OperatorNotified	Yes	Oio
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	ONO
Necessary Monthly Printout Taken	Yes	Q _N o	OperatorNotified	Ores	Ovo
	Spill Buckets	A :	O		
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	(ONo	OperatorNotified	es	X10
Are the Spill Bucket in good condition and free of damage/cracks	Yes	ONO	OperatorNotified	Oes	Ovo
Is Fill pipe cap tight and fill pipe free from any obstruction?	Fill Ports Yes	Ovo	OperatorNotified	Oes	Oio
Are Sumps Clean and free from water, debris, product etc?	Yes Sump	ONO	OperatorNotified	Ores	Oio
Under Dispen	ser Containme	ents (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	()No	OperatorNotified	(Dres	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPORTED FOLLOWING PROPER PROCE				AND REQUI	ATIONS
perator on Duty Name		Signature		Date	3-08-90
317-645-0215 tanksdat	ta@gmail.com			www.tanksda	ata.com