	3(DAYS WA	LKTHROUGH	INSPEC	TION	
Tanks Data						-
UST Facility I.D.((FID) # 521	Contact Number					
Facility Name (ITT60,	Contact email					
Address 4575 1137-th MU(16)72	Date of Inspection 0 - 0 5 - 0 C					
Operator on Duty Name	Name of the Person Conducting Inspection Current Conducting Inspection					
Op	erator Train	ing				
Operator Training current	Yes	No	OperatorNotified	Yes	(No	
Mily State S	ion/Notificat	ion Form	O	Over	Ola	
Is Registration current with correct owner, operator etc.	Yes	UNO .	OperatorNotified	Yes		
manager or design and the second seco	lease Detecti	On	CEIR	CIC	Other	
Release Detection Method	RAIG	J.IM	O D L L			
Make and Model	2		OperatorNotified	Wes	No	
Does it have paper?	res	No	OperatorNotified	Voc	No.	
Is it in Alarm mode?	Yes	SINO.		X	X,-	
Interstitial Monitoring Sensor Status Normal	(O) yes	QNo.	OperatorNotified	res	X, a	
Necessary Monthly Printout Taken	Yes	ONO	OperatorNotified	Oes	ONO	
	Spill Bucket	is ~				
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	No	OperatorNotified	Q)98	No	
Are the Spill Bucket in good condition and free of damage/cracks	Fill Ports	ONO	OperatorNotified	Ces	ONO	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	No	OperatorNotified	es	Olo	
	ping/STP Su	mps				
Are Sumps Clean and free from water, debris, product etc?	Yes	Olo	OperatorNotified	Yes	Olo	
Under Disp	enser Contai	nments (UDC)				
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified	Fes	No	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISE FOLLOWING PROPER PRO				S AND REQ	ULATIONS	
Operator on Duty Name		Signature	1 11 1 0 0	Date		
	sdata@gmail	com	VILLER	www.tanl	ksdata.com	
tunn.	Saure & Printers	9//				202225