

TRIENNIAL INSPECTION

Facility Name: Citgo

Test Date: 06/07/2022

Facility Address: 800 West 61st Avenue, Merrillville, IN, USA

Facility ID: N/A

UST CONTAINMENT SUMP INTEGRITY TESTING: HYDROSTATIC

Sump Name	Udc 1/2	Udc 3/4	Udc 5/6	Rul spill	Pul spill	Rul stp	Pul stp	
Product				Rul	Pul	Rul	Pul	
Test Type	Initial	Initial	Initial	Initial	Initial	Initial	Initial	
Sump Type	UDC	UDC	UDC	Spill	Spill	STP	STP	
Sensor Shutdown STP?	YES	YES	YES	NO	NO	YES	YES	
Clean of liquid/debris	YES	YES	YES	YES	YES	YES	YES	
VISUAL INSPECTION	PASS	PASS	PASS	PASS	PASS	PASS	PASS	
Test Start Time	9:00	9:00	9:00	9:00	9:00	10:00	10:00	
Test End Time	10:00	10:00	10:00	10:00	10:00	11:00	11:00	
Starting Water Level	12	12	12	12	12	24	24	
Ending Water Level	12	12	12	12	12	24	24	
Water Level Change (inches)	0	0	0	0	0	0	0	
HYDROSTATIC TEST RESULT	PASS	PASS	PASS	PASS	PASS	PASS	PASS	

Comments

Technician Name: Derek Terpstra

Technician Signature:



Dispatch # 311617

B&K Equipment completes testing and inspections per recommended practices of PEI RP1200-19