Tanks Data		3	0 DAYS W	ALK THROUGH	INSPEC	TION
UST Facility I.D.((FID)# 15 886		Contact Number				
Facility Name (/ T()		Contact email				
Address 800 mest 6184 Aug 4640		Date of Inspection 09/ -10 - 2075				
Operator on Duty Name			Name of the Person Conducting Inspection Crevebreet			
	Op	erator Traini				
Operator	Training current	Yes	ONo	OperatorNotified	Yes	ONo
	Registrat	ion/Notificat	ion Form			
Is Registration current with correct owner, operator etc.		Yes	ONO	OperatorNotified	Ves	Oio
Polones D		lease Detection	_		0.0	
	etection Method	ATG	CIM	BIR	Oic	Other
Make and Model () — (S			<u> </u>	0
Does it have paper?		Yes	No.	OperatorNotified	Yes	No.
Is it in Alarm mode?		Yes	ONO	OperatorNotified	Yes	QNo
Interstitial Monitoring Sensor Status Normal		Oes	ON0	OperatorNotified	()Yes	Olio
Necessary Mo	nthly Printout Taken	Yes	ONO	OperatorNotified	O'es	Olo
		Spill Buckets				
Are Spill Buckets Clean and free from water, debris, product etc?		Orcs	No	OperatorNotified	Oes	Oio
Are the Spill Bucket in good condition and free of damage/cracks		Yes	ONO	OperatorNotified	() es	Oio
		Fill Ports				
Is Fill pipe cap tight and fil	Il pipe free from any obstruction?	Yes	ONO	OperatorNotified	Oes	Olo
	and the state of the	ping/STP Sur	nps			
Are Sumps Clean and free	from water, debris, product etc?	Yes	Olo	OperatorNotified	(V) Yes	Olo
	egystet for deletation at 15 to 15 t	nser Contair	ments (UDC)		~~	
Are UDCs clean and free	from water, debris, product etc?	Yos	No	OperatorNotified	res	Oio
NOTE: ALL LIQUID/I	DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO				SAND REQU	LATIONS
Operator on Duty Name			Signature		Date	
317-645-0215	tankso	sdata@gmail.com			www.tanksdata.com	
						20220