Tanks Data	30 DAYS WALK THROUGH INSPECTION					
UST Facility I.D.((FID)# 15 88 Z	Contact N	Contact Number				
Facility Name (ITC)		Contact Pulliber				
Address 800 west 615t Avo 46						
Operator on Duty Name	Name of the Person					
	1	Conducting Inspection Cruerbareet				
	Operator Trai	The second secon	- and and a			
Operator Training current	Yes	No	OperatorNotified	Yes	(No	
To Registration approach with a second	gistration/Notifica	ation Form				
Is Registration current with correct owner, operator etc.		Û√No	OperatorNotified	()Yes	Olo	
Release Detection Method	Release Detec	tion				
Make and Model 1/12	ATG	SEIM	SIR	OIC	Other	
Does it have paper?	-5-300					
Is it in Alarm mode?	Yes	QNo.	OperatorNotified	Yes	QV0	
	Yes	QNo	OperatorNotified	Yes	QNo	
Interstitial Monitoring Sensor Status Normal Necessary Monthly Printout Taken	(V) Yes	ON ₀	OperatorNotified	Yes	ONo	
recessary Monthly Printout Taken	Xes	ONO	OperatorNotified	Yes	ONO	
Ara Crill Dualesta Class and Co. C.	Spill Bucke	ts				
Are Spill Buckets Clean and free from water, debris, product		(QNo	OperatorNotified	es	Oio	
Are the Spill Bucket in good condition and free of damage/cr		ONO	OperatorNotified	Oes	Olo	
Is Fill pipe cap tight and fill pipe free from any obstruction	Fill Ports					
as a mar proper out and man proper free from any obstruction		ONo	OperatorNotified	()es	Olo	
Are Sumps Clean and free from water, debris, product etc?	Piping/STP Su Yes	No	OnonatonNotified			
HANGER BERNER BERNE Berner Berner Berne	Dispenser Contai		OperatorNotified	Yres	ONO	
Are UDCs clean and free from water, debris, product etc'		No	OperatorNotified	Yes	Oko	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE FOLLOWING PROPER	DISPOSSED OFF	ACCORDING A CERTIFIED	TO EXISTING RULES	AND REQU	ILATIONS	
Operator on Duty Name		Signature		Date 1	5-10-2025	
317-645-0215	tanksdata@gmail.	com Jue	2	www.tanks		