

ESTABROOK LINE LEAK DETECTOR FUNCTIONALITY TEST

Facility Name: MERRILLVILLE CITGO/ROOP PETROLEUM INC Test Date: 06/20/2024
Facility Address: 6101 BROADWAY MERRILLVILLE IN 46410 Technician Name: Seamus Polanski
Facility ID: 9858 Technician Cert #: 021003

LEAK DETECTOR DETAILS

Pump	Make	Model	Serial #
1	Veeder-root	PIId	Na
2	Veeder-root	PIId	Na
3	Veeder-root	PIId	Na

ESTA BROOK EZY CHEK TEST DATA

Pump	Product Type	Metering Pressure	Holding PSI	Resiliency	Test Leak Rate ML/MIN	Opening Time (3-5)	Result PASS/FAIL
1	Regular	30	21	100	189	Pass	PASS
2	Premium	31	20	100	189	Pass	PASS
3	Diesel	30	21	100	189	Pass	PASS

Comments

Technician Name: Seamus Polanski

Technician Signature:



Dispatch # 403715

B&K Equipment completes testing and inspections per recommended practices of PEI RP1200-19