Tanks Data	3	30 DAYS W	ALKTHROUGH	INSPEC	TION
UST Facility I.D.((FID) # 7.26/3	Contact Number				
Facility Name Mofril	Contact email				
Address 6 85 1 Broodway 40410	Date of Inspection $06-10-2025$				
Operator on Duty Name	Name of the Person Conducting Inspection Greekback				
Op	erator Train	ning		<u> </u>	
Operator Training current	Yes	ONo.	OperatorNotified	Yes	ON0
Is Registration current with correct owner, operator etc.	Yes Yes	Oylo	OperatorNotified	Ores	Oło
	elease Detect	ion PIM	()BIR	OIC	Other
Release Detection Method	(YATG	O IN	Onn	O.	
Make and Model URTLS		ONo	OperatorNotified	Yes	Olo
Does it have paper?	Yes	No	OperatorNotified	Yes	Ŏ√o
Is it in Alarm mode?	Yes	\times .	OperatorNotified	Yes	No
Interstitial Monitoring Sensor Status Normal	Yes	No No	OperatorNotified	Yes	No
Necessary Monthly Printout Taken	Cycs Saill Bucket		Орегитоги		
	Spill Bucket	No	OperatorNotified	Ces	Oko
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	No	OperatorNotified	es	No
Are the Spill Bucket in good condition and free of damage/cracks	Fill Ports	0,0	Орогина		
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	No	OperatorNotified	() es	Oio
	oing/STP Su	mps		~	
Are Sumps Clean and free from water, debris, product etc?	Yes	Olo	OperatorNotified	Ves	Olo
Under Dispe		nments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	ONO	OperatorNotified		Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO	OSSED OFF CEDUE BY	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.		
perator on Duty Name		Signature	1	Date C	36-10-3
(B. 아프트) (B. 아트) 아들이 아들 아들는데 아트 (B. 아트) 아들이 하게 하는데 아름다면 아들이 아름이 있는데 아들이 아들이 아들이 아름이 있는데 아들이 없다면 하는데 없어요?	ata@gmail.com			www.tanksdata.com	