

30 DAYS WALK THROUGH INSPECTION

Tanks Data

UST Facility I.D. (FID) # 22613

Facility Name Mobil

Address 6851 Broadway, Merrillville

Operator on Duty Name

JN-46410

Contact Number

Contact email

Date of Inspection 04-09-25

Name of the Person Conducting Inspection Mohan Singh

Operator Training current

Operator Training

Operator Notified

Yes

No

Is Registration current with correct owner, operator etc.

Yes

No

Operator Notified

Yes

No

Release Detection

Release Detection Method

ATG

TIM

SIR

IC

Other

Make and Model

VN-7653505

Does it have paper?

Yes

No

Operator Notified

Yes

No

Is it in Alarm mode?

Yes

No

Operator Notified

Yes

No

Interstitial Monitoring Sensor Status Normal

Yes

No

Operator Notified

Yes

No

Necessary Monthly Printout Taken

Yes

No

Operator Notified

Yes

No

Spill Buckets

Are Spill Buckets Clean and free from water, debris, product etc?

Yes

No

Operator Notified

Yes

No

Are the Spill Bucket in good condition and free of damage/cracks

Yes

No

Operator Notified

Yes

No

Fill Ports

Is Fill pipe cap tight and fill pipe free from any obstruction?

Yes

No

Operator Notified

Yes

No

Piping/STP Sumps

Are Sumps Clean and free from water, debris, product etc?

Yes

No

Operator Notified

Yes

No

Under Dispenser Containments (UDC)

Are UDCs clean and free from water, debris, product etc?

Yes

No

Operator Notified

Yes

No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tanksdata@gmail.com

www.tanksdata.com

20220516