Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID)# 7 7 / 1 7	Contact Number				
Facility Name Molifo	Contact email				
Address 685/D20ddug46416	Date of Inspection $08-08-785$				
Operator on Duty Name	Name of the Person Conducting Inspection Guafacet				
Op	erator Train				
Operator Training current	Yes	ONo	OperatorNotified	Yes	Ovo
Registrat	tion/Notifica	tion Form		~	
Is Registration current with correct owner, operator etc.	Yes	Ovo	OperatorNotified	Ores	Olo
Re	lease Detect	ion		_	
Release Detection Method	SATG	& CIM	SIR	Oic	Other
Make and Model VR. TZS -	750	7			
Does it have paper?	Wes	ON <sub>0</sub>	OperatorNotified	Yes	Oto
Is it in Alarm mode?	Yes	ONO.	OperatorNotified	OYes	Oto
Interstitial Monitoring Sensor Status Normal	(X) Yes	No	OperatorNotified	Yes	Oio
Necessary Monthly Printout Taken	(X)Yes	No	OperatorNotified	Tes	Olo
	Spill Bucket	is			
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	(DNo	OperatorNotified	(Des	Olo
Are the Spill Bucket in good condition and free of damage/cracks	@Yes	No	OperatorNotified	es	Oio
	Fill Ports	_		_	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	Ovo	OperatorNotified	Oes	Oio
Pip	ping/STP Sur	mps		~	
Are Sumps Clean and free from water, debris, product etc?	Yes	Ø 1/0	OperatorNotified	(G)res	Oio
Under Disper			그리고 그는 가는 화장 중요를 하는 것들이 하는 것도 모든 선생님이 하는 것 같아요. 나를 하셨다.		
Are UDCs clean and free from water, debris, product etc?	Yes	(DNo	OperatorNotified	Yes	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO				AND REQU	ILATIONS
Operator on Duty Name		Signature	<u>e</u>	Date 6	8-08-3
317-645-0215 tanksd	ata@gmail.com			www.tanks	~
			$\leftarrow$		20220516