

5296 Breakers Way, Carmel, IN 46033

	www.tanksdata.com
igoremsize	tanksdata@gmail.com
9	(317)-300-6065

Date

10/8/25

UST Annual Walkthrough Inspection

1. UST Facility Information								
acility l.D.#: 22613								
UST Facility Name	Mobile							
UST Facility Physical Address	Street Address :	6851 Broadway	City:	Merrillville	Zip Code :	464		

2. Annual Inspection Checklist

Category	Description		Description		Description		n/a	Tank 1		Tank 2		Tank 3		Tank	4	Tank 5	Tani	c 6	Tank 7	Tai	nk 8
			Reg1		Reg2		Prem														
	Cap in good condition, seals tightly probe wire goes through	, hole sealed where		Yes	•	Yes	•	Yes	•		•].	•	. [V				
ATG Manhole	Junction box has cover, not corrodo wiring in good condition	ed; intrinsically safe		Yes	•	Yes	V	Yes	T		•].	V			•				
ATO MUNICIO	Manhole cover in good condition		Yes	•	Yes	V	Yes	•		•	. 🔻].	•	ļ. [lacksquare					
	Functionality Test Date :	10/8/25			•		•		•		•			•	[•				
	Single-walled spill containment mo tested within last 3 years	anhole tightness		Yes	v	Yes	•	Yes	•		•			v	. [-				
	Double-walled spill containment m tested within last 3 years OR inspec	V		•		v		•		•			•	ļ. [•					
Spill Bucket	Are spill buckets free of product, water and debris?			Yes	•	Yes	•	Yes	•		•	. 🔻		•]. [•				
	Are spill buckets free of damage/cracks?			Yes	•	Yes	•	Yes	v		•			•	<u> </u>		~				
	HSB Test Date :	9/20/23			•		•		•		•			•			•				
	Drop tube shutoff valve passes insp corrosion not present	pection & excessive	V		V		-		-		•			·			T				
Overfill	Ball float valve passes inspection, can be removed & excessive corrosion not present		~		•		•		•		•		<u> </u> -	•			•				
Prevention	Overfill alarm passes inspection			Yes	•	Yes	•	Yes	•		•	. •		•]. [-		$\overline{}$				
	OPV Test Date :	7/31/24			•		v		•		•			•			—				
	Galvanic Cathodic Protection test h within the past 3 years and the test			Yes	•	Yes	V	Yes	•		•			•			-				
Corrosion Protection	Impressed Current Cathodic Protection Conducted within the past 3 years of the Conducted within the past 3 years of the Conducted within the past 3 years of the Conducted within		V		•		•		•		•].	•			•				
	Tank Lining inspected as required and in good condition				•		•		•		•	. 🔽	<u> </u> -	-	<u> </u>	<u> </u>	$\overline{}$				
	CP Test Date :	1/23/25			•		•		•		•			•].		•				

Category Description		N/A	Tank	c1	Tank	Tank 2 To		Tank 3		Tank4			Tank 6		Tank 7		Tank 8	
	·		Reg1		Reg2		Prem											
	12 Months of RD printed and on site		Yes	•	Yes	•	Yes	₹		•	. [1		•	. [•		•
	Release Detection Report have issues in past months		No	•	No	•	No	lacksquare		V	. [•	. [T	. [1		•
Release Detection	ATG console has any history of alarm in past months		No	V	No	V	No	$\overline{oldsymbol{ol}}}}}}}}}}}}}}}$		•		-		•	. [-		•
Release Detection Type: ATG				•		•		$\overline{\blacksquare}$		•]		•	. [-		•
	Liquid and debris removed from sump?		Yes	V	Yes	~	Yes	Ī		v		•		T				v
Containment Sumps	Are containment sumps free of damage/cracks?		Yes	•	Yes	•	Yes	_		•	. [-		•		-].		•
	HSC Test Date :	~		¥		•		•		•				•	. [•
Stage I Testing	Verify that Stage I testing has been conducted and test results are passing	V		•		•		T		•	. []		•		-	Ī	v
		•	'									_						
Comments/	Deficiencies:																	

Name (Class A & B Operator) :	
Name (Person conducted the inspection) :	. losh Rider

N

Signature (Person conducted the inspection):