Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID) # 5007 9	Contact No	Contact Number			
Facility Name Marathan	Contact en	Contact email			
Address 77/9BRoddeys 40710	Date of Ins	Date of Inspection $07-06-203$			
Operator on Duty Name		Name of the Person Conducting Inspection Curry Conducting Inspection			
0	perator Train	ing		_	
Operator Training current	Yes	No	OperatorNotified	Yes	ONo
Is Registration current with correct owner, operator etc.	Yes	Oyo	OperatorNotified	Ores	Oio
Release Detection Method	elease Detection	On	OSIR	OIC	Other
Make and Model / R TLS - 2 Does it have paper?	OYes	(No	OperatorNotified	Yes	Oto
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	Olo
Necessary Monthly Printout Taken	Yes	ON _o	OperatorNotified	Tes	Ovo
	Spill Buckets			4	
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	ONO	OperatorNotified	es	Qvo
Are the Spill Bucket in good condition and free of damage/cracks	Yes Ports	ONo	OperatorNotified	Oes	Ovo
Is Fill pipe cap tight and fill pipe free from any obstruction?	Fill Ports Ores oing/STP Sum	ONO	OperatorNotified	Oes	O40
Are Sumps Clean and free from water, debris, product etc?	Oyes	No	OperatorNotified	Ores .	Olo
Under Disper	ser Containm	ents (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified	Yes	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PROC	OSSED OFF ACCEDUE BY A C	CCORDING CERTIFIED (TO EXISTING RULES A	AND REQUI	ATIONS
Operator on Duty Name		Signature		Date 0/	-00-100
나는 사람들이 얼마나 하는데 하는데 아니는 아니는데 나는데 아니는데 아니는데 아니는데 아니는데 아니는데 아니는데 아니는데 아니	ata@gmail.con	@gmail.com www.tanksdata.com			