

5296 Breakers Way, Carmel, IN 46033

	www.tanksdata.com
\bowtie	tanksdata@gmail.com
9	(317)-300-6065

Date

3/27/25

UST Annual Walkthrough Inspection

1. UST Facility Information												
Facility I.D. #:	50029											
UST Facility Name	Best Stop Marathon											
UST Facility Physical Address	Street Address :	7269 Broadway	City:	Merrillville	Zip Code :	46410						

2. Annual Inspection Checklist

Category	Description		N/A	A Tank 1		Tank 2		Tank 3		Tank	Tank4		5	Tank 6		Tank 7		Tank 8	
				Re	Reg		Prem		E-85		s								
	Cap in good condition, seals tightly, l probe wire goes through	hole sealed where		Yes	•	Yes	•	Yes	•	Yes	•		•		•		•		•
ATG Manhole	Junction box has cover, not corroded wiring in good condition	d; intrinsically safe		Yes	_	Yes	•	Yes	•	Yes	•		•	-	•	. [-		•
ATOMATHIOLE	Manhole cover in good condition			Yes	~	Yes	•	Yes	•	Yes	•		•	-	•		▼		•
	Functionality Test Date :	3/27/25			•	-	•		•		•		•		•	. [~		•
	Single-walled spill containment mar tested within last 3 years	nhole tightness		Yes	•	Yes	•	Yes	•	Yes	•		•		•		•		▼
	Double-walled spill containment ma tested within last 3 years OR inspecto		~	•	•	•	•	-	•		•		•	-	•		•		•
Spill Bucket	Are spill buckets free of product, wat	er and debris ?		Yes	•	Yes	•	Yes	•	Yes	•	. [•		•	. [▼		•
	Are spill buckets free of damage/cra	cks?		Yes	•	Yes	•	Yes	V	Yes	V		•		V	. [▼		▼
	HSB Test Date :	3/27/25			•	•	•		•		•		•		•	. [~		-
	Drop tube shutoff valve passes inspe corrosion not present	ection & excessive		Yes	•	Yes	•	Yes	•	Yes	•		•	-	•		-		▼
Overfill	Ball float valve passes inspection, ca excessive corrosion not present	ın be removed &	~		•	•	•	-	•		•		•		•		•		▼
Prevention	Overfill alarm passes inspection		~		lacksquare		•	ļ.	•		•		•		•	. [▼	. [•
	OPV Test Date :	3/27/25			•		•		•		•		•	.	•	. [~		•
	Galvanic Cathodic Protection test ha within the past 3 years and the test p		~		•		•		•		•	-	•		•		•		₽
Corrosion	Impressed Current Cathodic Protecti conducted within the past 3 years an		V	-	•	•	•		•		•		•		•	. [•		•
Protection	Tank Lining inspected as required an	nd in good condition	~		•		•	-	•		•		▼		•	. [▼		•
	CP Test Date :		V	•	•	Ē	•		•		•		•	·	•		~		•

Category	Description		Tank1		Tank 2		Tank 3		Tank4		Tank 5	Tank 6	Tank 7	Tank 8	
	12 Months of RD printed and on site		Yes	9	Yes	-	Yes		Yes	<u>-</u>	. 🔻	. 🔻	. 🔻	. 🔽	
	Release Detection Report have issues in past months		No		No	Н	No	Н	No		. 🔽	· 🗀		· <u> </u>	
Release Detection	ATG console has any history of alarm in past months		No	H	No	=	No		No		. 🔽	· 🔟	. 🔽		
			140		140		110		140	Ħ					
	Release Detection Type: ATG			_					•						
	Liquid and debris removed from sump?		Yes	✓	Yes	V	Yes	lacksquare	Yes					. 🔽	
Containment Sumps	Are containment sumps free of damage/cracks?		Yes	•	Yes	•	Yes	•	Yes	-					
	HSC Test Date :	~		•		•		_		•					
Stage I Testing	Verify that Stage I testing has been conducted and test results are passing	~		•	-	•		_		_					
Comments/I															
Name (Class A & B	Operator) ·														
Tame (State of the De															
Name (Person conducted the inspection) :							Josh	Ric	der						
Signature (Person o	\ \														