Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID)# 9578	Contact No	ımher			
Facility Name	Contact remail				
Address 30 2 W Dollar St Granfold St					
Operator on Duty Name					
	Name of the Person Conducting Inspection Guyleseet				
Op	perator Train				
Operator Training current	Yes	No	OperatorNotified	Yes	ONO
Registrat	tion/Notificat	tion Form		~	
Is Registration current with correct owner, operator etc.	Yes	No	OperatorNotified	Yes	Olo
	elease Detecti	on			
Release Detection Method	ATG	EIM	SIR	OIC	Other
Make and Model	00				
Does it have paper?	Yes	ON _o	OperatorNotified	Yes	ONO
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	ON0	OperatorNotified	Ores .	Olo
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	O'es	Olo
	Spill Buckets				
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	No	OperatorNotified	000	Olo
Are the Spill Bucket in good condition and free of damage/cracks	Yes	ONO	OperatorNotified	(Jes)	No
	Fill Ports	~		~	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	ON0	OperatorNotified	Oes	Olo
마스 그 사는 그리고 있는데 그리고 있는데 그는	ing/STP Sun				
Are Sumps Clean and free from water, debris, product etc?	Yes	Oyo	OperatorNotified	Ves	Oyo
Under Dispen		ments (UDC)		\sim	
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified	Cycs	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PROC	SSED OFF A CEDUE BY A	CERTIFIED C	O EXISTING RULES . ONTRACTOR.	AND REQUI	ATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tanksda	ata@gmail.co	m		www.tanksda	ata.com
					2022051