



5296 Breakers Way, Carmel, IN 46033

 www.tanksdata.com
 tanksdata@gmail.com
 (317)-300-6065

Date 4/3/25

AUTOMATIC TANK GAUGE FUNCTIONALITY TEST

Facility Name:	Citgo	Owner:	Neeru Inc.
Address:	302 W Joliet St	Address:	302 W Joliet St
City, State, Zip Code:	Crown Point, IN 46307	City, State, Zip Code:	Crown Point, IN 46307
Facility I.D. #:	9578	Phone #:	

This procedure is to determine whether the automatic tank gauge (ATG) is operating properly. See PEI/RP1200 Section 8.2 for the inspection procedure. This procedure is applicable to tank level monitor stems that touch the bottom of the tank when in place.

Tank Number	1	2	3	4	
Product Stored	Regular N	Regular S	Premium	Diesel	
ATG Brand and Model	INCON TS-2000	INCON TS-2000	INCON TS-2000	INCON TS-2000	
1. Tank Volume, gallons	9,552	5,786	4,022	3,009	
2. Tank Diameter, inches	91	91	64	64	
3. After removing the ATG from the tank, it has been inspected and any damaged or missing parts replaced?	Yes ☐	Yes ☐	Yes ☐	.	☐
4. Float moves freely on the stem without binding?	Yes ☐	Yes ☐	Yes ☐	.	☐
5. Fuel float level agrees with the value programmed into the console?	Yes ☐	Yes ☐	Yes ☐	.	☐
6. Water float level agrees with the value programmed into the console?	Yes ☐	Yes ☐	Yes ☐	.	☐
7. Inch level from bottom of stem when 90% alarm is triggered.	78	78	56		
8. Inch level at which the overfill alarm activates corresponds with value programmed in the gauge?	Yes ☐	Yes ☐	Yes ☐	.	☐
9. Inch level from the bottom when the water float first triggers an alarm.	2	2	2		
10. Inch level at which the water float alarm activates corresponds with value programmed in the gauge?	Yes ☐	Yes ☐	Yes ☐	.	☐
If any answers in Lines 3, 4, 5, or 6 are "No," the system has failed the test.					
Test Results	Pass ☐	Pass ☐	Pass ☐	Fail ☐	☐

Comment: The diesel probe was an older model and hardwired. Could not be tested bc it will not come all the way out of the tube.

Tester's Name : Josh Rider

Tester's Signature : 