		30 DAYS	WALK THROUG	H INSPE	CTION	
UST Facility I.D.((FID) # 05 2	Contact	Contact Number				
	Contact					
Address 307 W Tolio #54 46307		Date of Inspection 8-08-7				
Operator on Duty Name	Name of	Name of the Person Conducting Inspection  Guelle				
0	perator Tra					
Operator Training current	Yes	ONo	OperatorNotified	Yes	ON <sub>0</sub>	
# [AND NOTE OF A STATE OF A STAT	tion/Notific	ation Form		0	Oto	
Is Registration current with correct owner, operator etc.	Yes	ONO	OperatorNotified	()Yes	Oio	
	elease Detec	_	COTE	Orc	Other	
Release Detection Method	(2)ATG	CIM	SIR	OIC	O'unor	
Make and Model URTLS— 3	00		OnevetowNotified	Over	Olo	
Does it have paper?	Yes	QNo	OperatorNotified	Yes	X, .	
Is it in Alarm mode?	Yes	QNo	OperatorNotified	Yes	No.	
Interstitial Monitoring Sensor Status Normal	Yes	ONO	OperatorNotified	Yes	No	
Necessary Monthly Printout Taken	Yes	ONO	OperatorNotified	Yes	ONO	
	Spill Bucket	s				
are Spill Buckets Clean and free from water, debris, product etc?	Yes	(2No	OperatorNotified	es	Oio	
re the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	es	Olo	
	Fill Ports					
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	ONO	OperatorNotified	Oes	Oio	
Pipi	ng/STP Sur	nps				
Are Sumps Clean and free from water, debris, product etc?	Yes	(D)/10	OperatorNotified	Yes	Olo	
Under Dispens	er Contain	ments (UDC)				
Are UDCs clean and free from water, debris, product etc?	Yes	(SNo	OperatorNotified	Yes	Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOS FOLLOWING PROPER PROCE				AND REQU	LATIONS	
ator on Duty Name		Signature		Date		
317-645-0215 tanksdata@gmail.com				www.tanksdata.com		
	0.00				202205	