		30 1	DAYS W	ALK THROUGH	INSPECT	NOL
Tanks Data						
JST Facility I.D.((FID) # 16 225		Contact Number				
Facility Name AMOO		Contact email				
Address 1643 Penajaje Ave 46613		Date of Inspection $10-25-7075$				
Operator on Duty Name		Name of the Person Conducting Inspection  Grupping  Grupping  Conducting Inspection				
	Op	erator Training				
Operator Training current		OYes (	No	OperatorNotified	Yes	ONO
	Registrat	ion/Notification	Form			
Is Registration current with correct owner, operator etc.		Yes	No	OperatorNotified	Vres	ONO
D-1 T		lease Detection	A		0.0	O
Release Detection Method		ATG	<b>P</b> EIM	BIR	Oic	Other
마이트 보고 있는 것이 되었다. 그런	e and Model VE (C)	120	Ó.	O	0	0
Does it have paper?		Yes	QNo.	OperatorNotified	Yes	X1°
Is it in Alarm mode?		Yes	QNo No	OperatorNotified	Yes	QNo.
Interstitial Monitoring Sensor Status Normal		€ Yes	ON0	OperatorNotified	Yes	QNo.
Necessary Mo	onthly Printout Taken	Yes	ONO	OperatorNotified	Yes	Olo
		Spill Buckets				
Are Spill Buckets Clean and free from water, debris, product etc?		Yes	No	OperatorNotified	Ces	Olo
Are the Spill Bucket in good condition and free of damage/cracks		(2)Yes	ONO	OperatorNotified	Oes	Oio
		FNI Ports	0.		^	
Is Fill pipe cap tight and fi	Il pipe free from any obstruction?	Yes	ONO	OperatorNotified	Jes	Olo
	make the properties of the second	ping/STP Sum	· ( ).			
Are Sumps Clean and free	e from water, debris, product etc?	Yes	ONO	OperatorNotified	Ves	Oyo
	and the straight of the straig	enser Containn	nents (UD)	그 사람이 아이를 가장 하는데 아니라 사람이 되었다.		
Are UDCs clean and free	from water, debris, product etc?	Wc8	(No	OperatorNotified	l (Yes	Oyo
NOTE: ALL LIQUID/	DEBRIS OR WASTE MUST BE DISH FOLLOWING PROPER PRO				S AND REQ	ULATIONS
Operator on Duty Name			Signatu	re	Date	
317-645-0215	data@gmail.co	m /		www.tank	ksdata.com	
		55				202