Tanks Data		30	DAYS WA	LK THROUGH	INSPEC	TION
UST Facility I.D.((FID)# [627]	C	Contact Number				
Facility Name		ontact ema				
Address 643 Paja John	6/2 D	Date of Inspection / 9- 25- 25- 255				
Operator on Duty Name	N	Name of the Person Conducting Inspection Subscet				
	and the second s	tor Trainin				
Operator Training current		Yes	No	OperatorNotified	Yes	(No
	egistration	/Notificatio	n Form			
Is Registration current with correct owner, operator etc.	. (Yes	No	OperatorNotified	() Yes	Oio
	Releas	e Detection	1			
Release Detection Method	£	ATG	CIM	SIR	OIC	Other
Make and Model	7-39	8				
Does it have paper?	(0	Yes	ONo	OperatorNotified	Yes	Olo
Is it in Alarm mode?	(es	No	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	7	Yes	No	OperatorNotified	Yes	Oio
Necessary Monthly Printout Taken	2	Yes	No	OperatorNotified	Tes	No
	Spi	l Buckets	~			
Are Spill Buckets Clean and free from water, debris, produc	1	Yes	No	OperatorNotified	es	(No
Are the Spill Bucket in good condition and free of damage/c	and the second second second second	Yes .	No	OperatorNotified	es	No
		Il Ports				
Is Fill pipe cap tight and fill pipe free from any obstruction	on?	Yes	No	OperatorNotified	es	Olo
	***	STP Sum	os			
Are Sumps Clean and free from water, debris, product etc?	6	Yes	No	OperatorNotified	Ores	(No
Under	Dispense	r Containm	ents (UDC)			
Are UDCs clean and free from water, debris, product etc	0?	Yes	ONO	OperatorNotified	Tes	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE FOLLOWING PROPE	DISPOSS	ED OFF A	CCORDING T	O EXISTING RULES CONTRACTOR.	AND REQUL	ATIONS
Operator on Duty Name			Signature		Date	
317-645-0215	tanksdata	@gmail.com	n		www.tanksda	ta.com
	***********	0				20220516