

5296 Breakers Way, Carmel, IN 46033

	www.tanksdata.com
\boxtimes	tanksdata@gmail.com
9	(317)-300-6065

Date 7/11/25

LIQUID SENSOR FUNCTION	ONALITY TESTING
------------------------	-----------------

Facility Name: Food Mart Marathon					Owner	Owner: Food Mart Marathon								
Address: 3350 W Jonathan Moore Pike						Address: 3350 W Jonathan Moore Pike								
City, State, Zip Code: Columbus, IN 47201						City, State, Zip Code: Columbus, IN 47201								
Facility I.D. #:	239				Phone	Phone #:								
												_		
This procedure is to determine whethe fuel. See PEI/RP1200 Section 8.3 for the			ocated in the	int	erstitial space	e of	UST systems	ar	e able to det	tect	the presenc	:е о 	f water and	d ——
Sensor Location STP			STP 1 STP 2			STP 3 IM 1		IM 2						
Product Stored	Regular		Premium		Diesel	Diesel		Regular		Prem/DSL				
Type of Sensor	Non-Discri	•	Non-Discri	•	Non-Discri	•	Non-Discri	•	Non-Disc	r		•		•
Test Liquid	Water	•	Water	V	Water	•	Water	•	Water	•				•
Is the ATG console clear of any active or recurring warnings or alarms regarding the leak sensor? If the sensor is in alarm and functioning, indicate why.	Yes	•	No	•	No	•	Yes	•	Yes	•		*		•
Is the sensor alarm circuit operational?	Yes	•	Yes	•	Yes	•	Yes	•	Yes	•		•		•
Has sensor been inspected and in good operating condition?	Yes	•	Yes	•	Yes	•	Yes	•	Yes	•		•		•
When placed in the test liquid, does the sensor trigger an alarm?	Yes	•	Yes	•	Yes	•	Yes	•	Yes	•		•		•
When an alarm is triggered, is the sensor properly identified on the ATG console?	Yes	•	Yes	•	Yes	•	Yes	•	Yes	•		•		•
Any "No" answers indicates the sensor	fails the test.													
Test Results	Pass	•	Pass	_	Pass	•	Pass	•	Pass	•		lacksquare		•
Premium and diesel STP	's contain	liq	uid, tripping	y th	ne alarm. Bo	oth	alarms unt	rip	ped when	rer	noved fron	า S	TP.	
Comment														
									\bigcap			<u> </u>		
Tester's Name:	Josh R	ide	er	_	Teste	er':	s Signatu	ıre	e: <u>/</u> Ø	J		ノ		