

5296 Breakers Way, Carmel, IN 46033

	www.tanksdata.com
$\boxtimes$	tanksdata@gmail.com
3	(317)-300-6065

Date

7/21/25

## HYDROSTATIC SPILL BUCKET INTEGRITY TEST SINGLE- AND DOUBLE-WALLED VACUUM TEST METHOD

Facility Name: Exp	acility Name: Express Mart Marathon					Owner: Express Mart Marathon							
Address: 870 S State St					-	Address: 870 S State St						St	
City, State, Zip Code: North Vernon, IN 47265						City, State, Zip Code: North Vernon, IN 47265							
Facility I.D. #:	49			ŀ	Phone #:								
This procedure is to test the leak integ 6.3 for single-walled vacuum test me									5.2 f	or hydrostatic	tes	t method, Secti	ion
Tank Number		1		2		3		4					
Product Stored		Regular		Premium		Diesel		Kerosene					
Spill Bucket Capacity		5 gal		5 gal		5 gal		5 gal					
Manufacturer		OPW		OPW		OPW		OPW					
Construction		sw	•	sw	•	sw	•	sw	•		•	•	•
Test Type		Hydrostation	•	Hydrostati	•	Hydrostation	•	Hydrostatic	•		•	•	•
Spill Bucket Type		Product	•	Product	•	Product	•	Product	•		•	•	•
Liquid and debris removed from spill bucket?		Yes	•	Yes	•	Yes	•	Yes	•		•		•
Visual Inspection (No cracks, loose parts or separation of the bucket from the fill pipe.)		Pass	•	Pass	•	Pass	•	Pass	•		•	-	•
Tank riser cap included in test?		Yes	V	Yes	<b>-</b>	Yes	•	Yes	•		V	-	•
Drain valve included in test?		Yes	•	Yes	•	Yes	•	Yes	•		•	-	V
Starting Level		11"		11"		11.5"		11.5"					
Test Start Time		1:45pm		1:55pm		2:00pm		1:00pm					
Ending Level		11"		11"		11.5"		11.5"					
Test End Time		2:45pm		2:55pm		3:00pm		2:00pm					
Test Period		1 Hr		1 Hr		1 Hr		1 Hr					
Level Change		0		0		0		0					
Pass/fail criteria: Must pass visual inspection. Hydrat least 12 inches water column	ostatic: Wate	er level drop of les	s tha	ın 1/8 inch; Vacuu	ım:	single-walled only:	Mai	ntain at least 26 incl	hes v	vater column; Vacu	um	doub <b>l</b> e–walled: main	tain
Test Results		Pass	•	Pass	•	Pass	•	Pass	•		•	-	•
Comments:				<u>.</u>		<del></del> ,			\		_		
Tester's Name :	Jo	sh Rider			-	Tester's S	iq	nature :			<		