	30 DAYS WALK THROUGH INSPECTION					
UST Facility LD ((FED) # 2 4 2 97	Contact Number					
Facility Name (Joseph My Mark	Contact cossil					
Address 541 W 74-60 MUX 5+47765	Date of Inspection 03-22-2025					
	Name of the Person Conducting Inspection Guybroet					
	perator Traini					
Operator Training correct	()You	( )No	Operator Notified	()Xes	()No	
Is Registration current with correct owner, operator etc.	tion/Notificati ()Yes	los Epren Oio	Operator Notified	O)cos	0	
있었게 어느, 사람들은 말이 없는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하	elease Detection	in _				
Release Detection Method	<b>EXATO</b>	Om.		Ox		
Make and Model VR +US -	100					
Does it have paper?	(P)Yes	()No	OperatorNotified	()Yes	( <u>)</u> to	
Is it in Alarm mode?	67 Yes	()No	OperatorNotified	()Yes	0	
Interstitial Monitoring Sensor Status Normal	Yes	( )No	OperatorNotified	()res	Oio	
Necessary Monthly Printout Taken	ØYes .	ONO	OperatorNotified	Os	0.	
	Spill Buckets	6		_		
Are Spill Buckets Clean and free from water, debris, product etc?		The	OperatorNotified	X	X.º	
Are the Spill Bucket in good condition and free of damage/cracks	(A)Yes	0	OperatorNotified	Y		
Is Fill pipe cap tight and fill pipe free from any obstruction?	Fill Ponts O'es	Oio	Operator Notified	Os	0	
	ping/STP Sun	ups				
Are Sumps Clean and free from water, debris, product etc?	<b>U</b> Kes	Pio	Operator Notified	( Of You	( )\o	
	nser Contain					
	OYes	(Q)No	OperatorNotified	하다 하시 사람들은 사람이 얼마를 가게 했다.	()%	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO	OSSED OFF A	CERTIFIED	TO EXISTING RULES	AND REQU	ILATIONS	
Operator on Duty Name		Signature	1	Date		
	data@gmail.or	M28 /	-	www.tanks	data.com	
					202	