Tanks Data		30	DAYS WA	ALK THROUGH	HINSPEC	TION
UST Facility I.D.((FID)# 7.4287,		Contact Number				
Facility Name (surtry, range		Contact email				
Address 541WI	Date of Inspection 10-13-(0)					
Address 59 Wwalnut St 97 167 Operator on Duty Name		Name of the Person Conducting Inspection Conducting Inspection				
	0	perator Training		/		<u> </u>
Operator Training current		OYes (No	OperatorNotified	()Yes	○No
Is Registration current with correct owner, operator etc.		Ation/Notification Yes	○No	OperatorNotified	Ores	Oto
	R	elease Detection	~!			
Release Detection Method		CATG O	CIM	SIR	Oic	Other
Make and Model VRTL. Does it have paper?		35 G Yes)No	OperatorNotified	OYes	Qio
Is it in Alarm mode?		Xes (No	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal		Yes	No	OperatorNotifled	Ores .	Olo
Necessary Monthly Printout Taken		Yes	No	OperatorNotified	Tes	Olo
		Spill Buckets	_			
Are Spill Buckets Clean and free from water, debris, product etc's			No	OperatorNotified	A)es	Olo
Are the Spill Bucket in good condition and free of damage/cra			No	OperatorNotified	es	Oio
		Fill Ports	\leq			
Is Fill pipe cap tight and fil	I pipe free from any obstruction?	Yes	O ₁₀	OperatorNotified	Oes	Olo
		iping/STP Sump	,			
Are Sumps Clean and free	from water, debris, product etc?	Yes	(No	OperatorNotifled	Yes	Olo
		enser Containme	thts (UDC)			
Are UDCs clean and free	from water, debris, product etc?	OY'es ,	(No	OperatorNotified	Cres	Olo
NOTE: ALL LIQUID/I	DEBRIS OR WASTE MUST BE DISE FOLLOWING PROPER PR	POSSED OFF AC	CORDING T	the first water and the second state of the second state of the second	AND REQU	LATIONS
Operator on Duty Name			Signature		Date	
317-645-0215					www.tanksdata.com	
			1			20220