Tanks Data	30 DAYS WALK THROUGH INSPECTION					
UST Facility I.D.((FID) # 7 2.7	Contact Number					
Facility Name 511NO (0	Contact email					
Address 765 NS satelt 47266	Date of Inspection (28 - 22 - 2025					
Operator on Duty Name	Name of the Person Conducting Inspection Cuybreet					
Op	perator Train	the state of the s				
Operator Training current	Yes	ONo	Operator Notified	()Yes	(No	
Registra	tion/Notifica	tion Eorm				
Is Registration current with correct owner, operator etc.	Yes	(No	OperatorNotified	Ves	Oio.	
	elease Detect	ion		0	0-	
Release Detection Method	ATG	CEIM	SIR	Occ	Unter	
Make and Model (/ / / > -)	76			<u> </u>		
Does it have paper?	(X)Yes	No	OperatorNotified	Yes	X40	
Is it in Alarm mode?	OYes	(d)No	OperatorNotified	Ves	QNo.	
Interstitial Monitoring Sensor Status Normal	(A) cs	(No	OperatorNotified	()Yes	ONO	
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Yes	ONO	
	Spill Bucket	s ,				
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	9 No	OperatorNotified	es	Oio	
Are the Spill Bucket in good condition and free of damage/cracks	Ves	No	OperatorNotified	es	Oio	
	Fin Ports					
Is Fill pipe cap tight and fill pipe free from any obstruction?	OYes	ONO	OperatorNotified	Oes	Olo	
Pig	ping/STP Sur	nps				
Are Sumps Clean and free from water, debris, product etc?	Yes	(D)No	Operator Notified	Wes	Oio	
Under Disper	nser Contain	ments (UDC)				
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified	Tes	Oio	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO				AND REQU	LATIONS	
Operator on Duty Name		Signature		Date		
317-645-0215 tanksd	lata@gmail.com			www.tanksdata.com		
		1	2		200	